



Laboratory Specialists
For over 30 years



Industrial Furniture Case Study

Client:

REGAIN
Polymers Limited

Location: Castleford

Project: Refurbishment of existing site

Duration: 10 weeks

Reason for works:

To bring the existing labs up to date and to showcase the companies capabilities to potential customers.

Scope of works:

Strip out and demolition of existing furniture and room layouts.
Creation of new lab areas.

The full programme of works consisted of:

- Furniture & worktops
- Building works - including new partitioning
- Decorating
- Door entry system
- Plumbing
- Drainage
- Gases - including Nitrogen & Oxygen
- Electrical
- Extraction system
- Air conditioning – heating & cooling
- Suspended ceilings
- Flooring

Outcome:

Job delivered on time and budget. The new labs have allowed Regain Polymers to proceed with the expansion of their company in terms of output and increasing their product range.

